Georgia Tech Analog, Power, and Energy IC Research

Safety Information

- 1. Environmental Health and Safety (EHS): www.ehs.gatech.edu.
- 2. Required Lab, Laser, & Right-to-Know Training: users.ece.gatech.edu/rincon-mora/research.
- 3. Probe Station: Use the safety goggles provided when the laser is on.
- 4. Gas Tanks: Use the gloves provided when handling gas tanks.
- 5. Emergency: Call Campus Police at (404) 894-2500 or EHS at (404) 216-5237.

Lab Rules

- 1. No food, drinks, or personal items allowed in VL 308.
- 2. No open-toe shoes, shorts, or pants with holes can be used in VL 308.
- 3. Confine all personal items to your assigned office.
- 4. Confine test equipment and components you use to your workbench.
- 5. Confine all your work to your assigned office and assigned workbench.
- 6. No items in your office should rise above the level of the cubicle wall.
- 7. Shut lights and equipment off at the end of each day (unless experiments run overnight).
- 8. Use center tables for schematics and layouts only (and only temporarily).
- 9. Clean up the center tables and solder and probe stations after using them.
- 10. No equipment is to leave Van Leer 308.
- 11. Throw away boxes and garbage as soon as they are generated.
- 12. Consult with fellow team members before moving equipment from their benches.
- 13. Do not re-arrange the lab (or move furnishings) without prior consent from your advisor.
- 14. Before ordering parts, check the cabinets for existing parts.
- 15. When ordering parts, re-stock the component cabinet carefully with leftover parts.
- 16. Keep lab doors closed at all times (to keep anyone from stealing lab or personal items).
- 17. Help keep all unassigned workbenches and offices and common areas clean and organized.
- 18. Lab Coordinator has no jurisdiction over assigned workbenches and offices.
- 19. Lab Coordinator must keep all unassigned workbenches and offices and common areas clean and organized and inspect visually fire extinguishers every month.